2/3/2017 Hobbs 2274.5 Installed dual camera ports IAW STC # SA1010NW. See W & B, Equipment list and 337 this date. POH revised. Cabin placard installed. All components field = fabricated per engineering drawings, orders, and revisions. Installed and tensioned elevator as well as elevator, aileron and rudder trim cables per Piper maintenance manual. Installed 2 ea potter Brumfield PN WX23X1A1G50 ckt brakers on pilot panel. Routed 2 strands # 10 wire from each CB to each outlet on the side wall opposite the cabin door. At cabin roof Aprox FS 160, Installed "Aero Antenna Technology" GPS antenna for survey equipment PN: AT 1675-80W-tncf-000-RG-43-NM SN: 6052. Routed 2 strands RG143 coax to bkhd connectors on the side wall opposite the cabin door. Repositioned Com 2 antenna from FS 153 to 113. Collins com and nav radio removed from panel. Connector plates and cables coiled bagged and stowed aft of the instrument panel center section. Work completed 1AW AC 43.13-1B, Chapter 11 Operational flight test completed. Jay D. Hoogstra A&P / IA 3671902. 9 0 747990)